



Forane® 409A

Pressure-Temperature Chart

Saturation Temperature [°F]	Liquid Pressure [psig]	Vapor Pressure [psig]
-50	12.4	17.2
-45	9.7	15.2
-40	6.8	13.1
-35	3.5	10.7
-30	0.0	8.1
-25	2.0	5.1
-20	4.1	1.9
-15	6.5	0.8
-10	9.0	2.8
-5	11.8	4.9
0	14.8	7.2
5	18.1	9.7
10	21.7	12.5
15	25.5	15.4
20	29.6	18.7
25	34.0	22.2
30	38.7	26.0
35	43.8	30.1
40	49.2	34.5
45	54.9	39.2
50	61.0	44.3
55	67.6	49.8
60	74.5	55.6
65	81.8	61.9
70	89.5	68.6
75	97.7	75.8
80	106.4	83.4
85	115.5	91.5
90	125.2	100.2
95	135.3	109.4
100	146.0	119.2
105	157.2	129.6
110	169.0	140.6
115	181.4	152.3
120	194.4	164.7
125	208.0	177.8
130	222.3	191.6
135	237.2	206.3
140	252.9	221.8
145	269.3	238.2
150	286.4	255.5

Red numerals = inches Hg below 1 atm